

English

# **Instruction and Operation Manual**



Display



# .SUO

Dear Customer,

Thank you for choosing our product.

The operating instructions must be read in full and carefully observed before starting up the device. The manufacturer cannot be held liable for any damage which occurs as a result of non-observance or noncompliance with this manual.

Should the device be tampered with in any manner other than a procedure which is described and specified in the manual, the warranty is cancelled and the manufacturer is exempt from liability.

The device is destined exclusively for the described application.

SUTO offers no guarantee for the suitability for any other purpose. SUTO is also not liable for consequential damage resulting from the delivery, capability or use of this device.

### **Table of Contents**

1 Safety Instructions	4
2 Registered trademarks	
3 Application	
4 Features	
5 Technical Data	
5.1 General.	
5.2 Electrical Data	
5.3 Input-Signals	
5.4 Output-Signals	
6 Dimensional Drawing	
7 Installation	
7.1 Installation Requirements	10
7.2 Electrical Connection	10
7.2.1 AC Power Supply and Alarm Connection (A1640)	11
7.2.2 DC Power Supply and Alarm Connection (A1641)	11
7.2.3 Signals at Back Terminals	12
7.2.4 Connection of SUTO Sensors	
7.2.5 Connection of Third-Party Analog Sensors	14
8 Configuration	15
9 Operation	16
9.1 Description of Display Icons	16
9.2 Sensor Setting	17
9.3 Alarm Setting	
9.4 System Status and Settings	
9.5 Service Setting	17
10 Signal Input	
10.1 Digital Input	
10.2 Analog Input	
11 Signal Outputs	
11.1 Alarm Output	18
12 Optional Extra Accessories	
13 Maintenance	
14 Disposal or Waste	18

# **1** Safety Instructions

# Please check if this instruction manual accords to the product type.

Please observe all notes and instructions indicated in this manual. It contains essential information which have to be observed before and during installation, operation and

maintenance. Therefore this instruction manual has to be read carefully by the technician as well as by the responsible user / qualified personnel.

This instruction manual has to be available at the operation site of the display at any time. In case of any obscurities or questions, regarding this manual or the product, please contact the manufacturer.



### WARNING!

Compressed air!

#### Any contact with quickly escaping air or bursting parts of the compressed air system can lead to serious injuries or even death!

- Only use pressure tight installation material.
- Avoid that persons get hit escaping air or bursting parts of the instrument.
- The system must be pressureless during maintenance work.



#### WARNING!

Voltage used for supply!

Any contact with energized parts of the product, may lead to a electrical shock which can lead to serious injuries or even death!

- Consider all regulations for electrical installations.
- The system must be disconnected from any power supply during maintenance work.
- Any electrical work on the system is only allowed by authorized qualified personal.



#### ATTENTION!

Permitted operating parameters!

Observe the permitted operating parameters, any operation exceeding this parameters can lead to malfunctions and may lead to damage on the instrument or the system.

- Do not exceed the permitted operating parameters.
- Make sure the product is operated in its permitted limitations.
- Do not exceed or undercut the permitted storage and operation temperature and pressure.
- The product should be maintained and calibrated frequently, at least annually.

#### **General safety instructions**

- It is not allowed to use the product in explosive areas.
- Please observe the national regulations before/during installation and operation.

#### Remarks

• It is not allowed to disassemble the product.



# ATTENTION!

Measurement values can be affected by malfunction!

The product must be installed properly and frequently maintained, otherwise it may lead to wrong measurement values, which can lead to wrong results.

#### Storage and transportation

- Make sure that the transportation temperature of the display is between -30 ... +70°C.
- For transportation it is recommended to use the packaging which comes with the display.
- Please make sure that the storage temperature of the display is between 0 ... +40°C.

SUŰ



- Avoid direct UV and solar radiation during storage.
- For the storage the humidity has to be <90%, no condensation.

# 2 Registered trademarks

Trademark	Trademark owner
SUTO <sup>®</sup>	SUTO ITEC
MODBUS®	Modbus Organization, Hopkinton, USA
Android™, Google Play	Google LLC

# **3** Application

The S320 display can display all relevant parameters (flow, dew point, pressure, temperature, power consumption, compressor status etc.) in a compressed air system.

The S320 display and data logger is not developed to be used in explosive areas. For the use in explosive areas please contact the manufacturer.

The S320 display and data logger is mainly used in compressed air systems in industrial environment.

# 4 Features

- Graphic display for easy user interface.
- Flexible power supply: 100 V ... 240 VAC / 50 ... 60 Hz or 18 ... 30 VDC.
- One input for SUTO SDI sensors.
- One input for analog sensors: 0 ... 20 mA, 4 ... 20 mA, 0 ... 10 V.
- Two relay outputs for alarm.
- USB interface for configuration with S4C software.
- Wall or panel mountable casing.
- Optional alarm on display.

# **5** Technical Data

#### 5.1 General

CE	
----	--

CE	
Operating temperature	0 50°C
Housing material	ABS
Protection class	IP65
Dimensions	See dimensional drawing on the next page
Display	Graphic display, 220 x 140 pixels with back light
Interface	USB to PC
Keyboard	4 keys
Weight	0.52 kg

#### 5.2 Electrical Data

Power supply	100 240 VAC, 15 VA (option A1640) 18 30 VDC, 20 W (option A1641)
Sensor supply	24 V, 10 W

### 5.3 Input-Signals


Digital input	1 x SDI for SDI input of SUTO sensors
Analog input	1 x 0 20 mA or 1 x 4 20 mA or 1 x 0 10 V


### 5.4 Output-Signals


Alarm output	2 relays, 230 VAC, 3 A
--------------	------------------------


# 6 Dimensional Drawing

Panel mounting (standard)











Wall mounting





# .ട്രാം

# 7 Installation

Please make sure that all components listed below are included in your package.

Qty Description	Item No.
1 S320 Panel with ordered options and if ordered with casing	D500 0320
1 Instruction manual	No P/N


### 7.1 Installation Requirements

The instrument can either be mounted into a panel or if ordered with the optional wall casing on a wall. Please observe the drawings in chapter 6 for details. The housing of the S320 must be fixed on the wall using suitable dowels and screws.


# 7.2 Electrical Connection

### Terminal block layout at back side


The following diagram is the terminal block layout at S320 back side.



#### 7.2.1 AC Power Supply and Alarm Connection (A1640)



#### 7.2.2 DC Power Supply and Alarm Connection (A1641)



#### 7.2.3 Signals at Back Terminals

Terminal	Pin	Signal	Description			
	8	+V <sub>b</sub>	Positive sensor supply			
	7	-V <sub>b</sub>	Negative sensor supply			
	6	SDI	Digital communication signal from sensors			
G	5	Iin	4 20 mA signal from sensor			
G	4	+P	Active pulse signal from flow sensor			
	3	-V <sub>b</sub>	Negative signal connection to PLC			
	2	Iout	4 20 mA signal to PLC			
	1	-V <sub>b</sub>	Negative signal connection to PLC			
	6	-V <sub>b</sub>	Negative signal connection to PLC			
	2	-V <sub>b</sub>	Negative signal connection to PLC			
н	4	-V <sub>b</sub>	Negative signal connection to PLC			
	3	-V <sub>b</sub>	Negative signal connection to PLC			
	2	Piso	Isolated pulse output pin 2, NO			
	1	Piso	Isolated pulse output pin 1, NO			
	5	+V <sub>b</sub>	Positive analog sensor supply			
	4	-V <sub>b</sub>	Negative analog sensor supply			
I	3	+20 mA	Positive current input			
-	2	SGND	Signal ground (internally connected to $-V_{_{b}}$ of			
			terminal I)			
	1	+10 V	Positive voltage input			

#### Remarks

- In order to use the isolated pulse output at terminal H its required to have the active pulse output of the flow sensor connected to terminal G, pin 4.
- 4 ... 20 mA signals from flow sensor or dew point sensors can be looped through the G terminal pin 5 + 2. The external device (PLC or mA-meter) negative signal is connected to pin 1.
- Analog sensors are connectable to terminal I.

#### 7.2.4 Connection of SUTO Sensors

	S32	20	S401/ S421	S450/ S452	S430	S211*/S215 */S220*	S120/S130 /S132	Cable
	Pin	Signal	Pin	Pin	Pin	Pin	Pin	Color
	1	-V <sub>b</sub>						
U T	2	I <sub>out</sub>						
Terminal	3	-V <sub>b</sub>						
erm	4	N/A						
Ĕ	5	N/A						
	6	SDI	A.1	4	A.1	3	A.1	brown
	7	-V <sub>b</sub>	A.2	3	A.2	2	A.2	white
	8	+V <sub>b</sub>	A.3	2	A.3	1	A.3	blue

\* The dew point sensor type must be equipped with SDI: S699 1xxx or S699 2xxx.

Connection via analog 4...20 mA input

	<b>S</b> 32	20	S401 / S421	S450/ S452	S430	S211*/S215* /S220*	S120/S130 / S132	S415/ S418
	Pin	Signal	Pin	Pin	Pin	Pin	Pin	Pin
_	1	V <sub>in</sub>						
	2	GND						
Terminal	3	I <sub>in</sub>	B.4	10	B.4	4	B.4	A.4
Ter	4	-V <sub>b</sub>	B.5+A. 2* <sup>2</sup>	9+3*2	B.5+A .2* <sup>2</sup>	2	B.5+B.2* <sup>2</sup>	A.1+A.2 *2
	5	+V <sub>b</sub>	A.3	2	A.3	3	B.3	A.3

\* The dew point sensor type must be 3-wire type: S699 2xxx.

\*<sup>2</sup> By connecting it like this, the isolated analog output becomes nonisolated, you have to bridge -Vb and I- to connect it as 3-wire sensor.

#### Looping the analog output of SUTO dew point sensors to a PLC


It is possible to connect a SUTO dew point sensor via SDI to the S320 and at the same time use the analog output of the SUTO sensor to be connected to an external PLC or analog input card.

See the below connection table.

# .SU0


S320			S211*/S215*/ S220*	External PLC / Analog Module	Cable
Terminal G	Pin	Signal	Pin		Color
	1	-V <sub>b</sub>		to I-/ $I_{out}$ of PLC	
	2	$\mathbf{I}_{out}$		to $I+/I_{in}$ of PLC	
	3	-V <sub>b</sub>			
	4	N/A			
	5	$\mathbf{I}_{in}$	4		black
	6	SDI	3		brown
	7	-V <sub>b</sub>	2		white
	8	+V <sub>b</sub>	1		blue

#### **Connection Scheme**



# 7.2.5 Connection of Third-Party Analog Sensors

S320			External analog sensor
	Pin	Signal	Process signal
Terminal I	1	$V_{\text{in}}$	Voltage (0 1 V / 0 10 V)
	2	GND	Signal ground (internally connected to I.4 -V <sub>b</sub> )
	3	$\mathbf{I}_{in}$	Current (0 20 mA / 4 20 mA)
	4	-V <sub>b</sub>	Negative Power supply connection
	5	$+V_{b}$	Positive Power supply connection (24 VDC)



### 8 Configuration

The S320 is delivered with specific customer settings according to the order.

In order to simplify the user interface not all settings but most of it are accessible via the user interface, instead a PC software can be used. This software is called S4C which can be downloaded from the company web page.


To change certain or all settings by the user, S320 can be connected to the PC via the USB interface. After starting S4C all device settings are accessible.

All settings are stored permanently inside of the S320 and do not need to be entered again, unless the user wants some changes. Some setting for the dew point and flow sensor can also be done at the user interfacer of S320.

# .SU0

# 9 Operation

# 9.1 Description of Display Icons



The display can illustrate different measurement values like shown in the graphic. Please use the buttons for changing settings.

Back	<ul> <li>Use this key to exit the current menu level.</li> <li>Use it to leave all setting state without saving the change.</li> </ul>
	<ul> <li>Use this keys to browse and select different items in menu and scroll through different pages of measurement value display.</li> <li>Use this key to alter or adjust the setting option or numbering.</li> </ul>
Enter	<ul> <li>Use this key to enter to submenu or next menu level of the current selected menu item.</li> <li>To confirm the setting change or enable an option in all setting state.</li> </ul>

After pressing the enter button, different submenus can be selected. The particular submenus will be explained in the next chapters.

#### 9.2 Sensor Setting

After selecting "Sensors" the next screen will show which kind of sensors are programmed at which terminal. Changes can be done individually for each sensor, by selecting the terminal where the sensor is connected to.

#### 9.3 Alarm Setting

The S320 has two alarm relay outputs. It is possible to set the value and the direction of the value for "Alarm 1" and "Alarm 2".

#### 9.4 System Status and Settings

Please press the "System" button for the following submenus:

Device Info	It will show different system information like device type, device serial number, firmware version, hardware version etc.
LCD Contrast	Contrast of the display can be changed.
Reset	In case sensors have been changed its recommended to use this function in order to update system settings.
Language	Please choose the desired language.

#### 9.5 Service Setting

Contact information of service company ban be set in this submenu.

### **10 Signal Input**

#### **10.1 Digital Input**

The display has one sensor input for SUTO flow / dew point sensor.

#### **10.2 Analog Input**

The display has one analog input for SUTO pressure / temperature sensor or further sensors (0  $\dots$  20 mA / 4  $\dots$  20 mA / 0  $\dots$  10 V).

# **11 Signal Outputs**

#### 11.1 Alarm Output

The display has two alarm relay outputs (230 VAC, 3 A).

### **12 Optional Extra Accessories**

The following extra accessories are optional:

- Sensor cable 5 m with M12 connector, open wire.
- Sensor cable 10 m with M12 connector, open wire.
- Power cable with mains plug, 1.8 m.

### 13 Maintenance

To clean the sensor and its accessories it is recommended to use moist cloth only.



#### **ATTENTION!**

Do not use isopropyl alcohol to clean the display!

# 14 Disposal or Waste



Electronic devices are recyclable material and do not belong in the household waste.

The sensor, the accessories and its packings must be disposed according to your local statutory requirements. The dispose can also be carried by the manufacturer of the product, for this please contact the manufacturer.



# SUTO iTEC GmbH

Grißheimer Weg 21 D-79423 Heitersheim Germany

# SUTO iTEC (ASIA) Co., Ltd.

Room 10, 6/F, Block B, Cambridge Plaza 188 San Wan Road, Sheung Shui, N.T. Hong Kong

Tel: +49 (0) 7634 50488 00 Email: <u>sales@suto-itec.com</u> Website: <u>www.suto-itec.com</u> Tel: +852 2328 9782 Email: <u>sales.asia@suto-itec.com</u> Website: <u>www.suto-itec.com</u>

# SUTO iTEC Inc.

5460 33rd St SE Grand Rapids, MI 49512 USA

Tel: +1 (616) 800-7886 Email: <u>sales.us@suto-itec.com</u> Website: <u>www.suto-itec.com</u>

All rights reserved ©

Modifications and errors reserved. S320\_im\_en\_2023-1